





Fräsmaß / Worktop hole opening size:

Standard Version:

$X = \text{Länge / Length} - 5$

$Y = \text{Breite / Width} - 5$